



Global Auto Guard Inspection Report

2015 Volkswagen Amarok

Full Description: Volkswagen Amarok 2H
MY15 TDI420 Highline Cab Chassis
Dual Cab 4 Dr Auto 8sp
4MOTION Perm 1158kg 2.0DTT

Date: 23-01-2019

VIN: WV1ZZZ2HZFA029355

Registration: 2SERV

Odometer: 96,000 KM

Inspection Location: Brookwater, QLD 4300



Vehicle Specifics

Engine Number:	CSH112823	Exterior Colour:	2t-Deep Black Pearl Effect
Variant:	TDI420 Highline	Interior Colour:	Wb
Build Date:	2/2015	Number of Keys:	2
Compliance Date:	2/2015	Last Service:	6/2018 – 80,000km
Model Year (MY):	MY15	Next Service:	6/2019 – 90,000km
Registration Expiry:	25-03-2019	Tyre Condition:	Needs 1 Tyre
Body Type:	Cab Chassis	Repair Evidence:	No
Drive Train:	4x4 Constant		
Cylinders:	4 Cylinders		
Fuel:	Diesel		
Transmission:	Automatic		



Global Auto Guard Inspection Report

Factory Specifications

Vehicle class differentiation 2H0 / Vehicle class differentiation units/platform components
Trailer hitch / Trailer hitch
Special identification plate / Identification plates
Alloy spare wheel original equipment tires / Spare wheel/breakdown set
Labels for country group 6 / Labels
Power steering / Steering
Standard wheel bolts / Lockable wheel bolts
Tool kit and jack / Tool kit and jack
Additional front underbody guard / Front underbody guard
Four wheel drive / Drive layout
Differential lock / Differential lock
Initial standard fuel filling / Fuel quantity for initial filling
Delivery equipment for shipment / Delivery equipment
Additional exterior noise suppression / Exterior noise suppression measures
16-inch chassis / Chassis
Body-coloured bumpers / Bumper
Leather multi-function steering wheel / Steering wheels
Child seat anchor for child seat system ISOFIX / Additional child seat anchors
Centre console / Centre console
Leather parts scope / Leather parts scope
Three rear headrests / Rear headrests
Lockable comfort tailgate / Rear gates/tailgate
Standard seat, front right / Front seat, right
Standard seat, front left / Front seat, left
3-seater bench seat / Second row of seats
Windshield in heat-insulating glass / Windshield glass type
Radio remote controlled central locking operated from inside and safe securing / Door and lid locking system
Cup holder in cab / Cup holder
Power windows / Window regulator
Air bag for driver and front seat passenger / Air bag
Side air bag front curtain air bag / Side air bag
Carpet floor covering in cab / Floor coverings in cab
Carpet floor covering in passenger compartment / Floor coverings in passenger and load compartment
Body measures for increased safety requirements / Body measures
Carrier frequency 433.92 MHz-434.42 Mhz / Carrier frequency for radio remote control



Global Auto Guard Inspection Report

SYSTEMS INSPECTED

BODY

- Panels
- Doors / Locks
- Glass / Mirrors
- Interior Condition
- Seats / Belts
- Body Repair Evidence

ELECTRICAL

- External Lights
- Battery
- Wipers / Washers
- Horn
- Instrument Cluster
- Heater
- A/C
- Central locking
- Controls / Windows / Seats

UNDERBODY

- Exhaust
- Front / Rear Suspension
- Shock Absorbers
- Steering System
- Wheels / Bearings
- Transmission / Operation
- Drive line / CV / Universals
- Brake System – Visual non invasive
- Tire Wear
- Spare Tire / Jacking equipment

ENGINE / FLUID LEVELS

- Fuel System
- Cooling System / Fluid / Level
- Brake System / Fluid / Level
- Steering System / Fluid / Level
- Oil System / Fluid / Level
- Ignition System
- Airflow System
- Mounts
- Belts / Pulleys / Noises
- Exhaust Fumes / Oil Leaks

ROAD TEST

- Vehicle Start
- Steering / Suspension
- Noises
- Drive Train
- Warning Lights
- Temperature
- Brake Operation

OTHER

- Service History
- Owner Manual
- Keys



Global Auto Guard Inspection Report

DISCLAIMER

This is a visual, non-mechanical inspection only. Vehicle components will not be removed from the vehicle during the inspection. You acknowledge that while the inspectors use accepted methods for fault detection, these methods may not identify all faults. The inspection includes the vehicles Body, Interior, Exterior, Electrical Systems, Engine systems, Cooling Systems, Exhaust Systems, Braking Systems, Fuel Systems, Steering & Suspension Systems, Safety Systems, Transmission Systems, Final Drive Systems, Chassis, Understructure and a Road test, where possible.

The representative or company carrying out the inspection will not be responsible for defects found before or after the inspection is carried out, items may not be visually identifiable at the time of inspection.

The inspection is only current as at the time and date of issue. It is not a roadworthy certificate and cannot be used as one. Inspectors are not required to follow up manufacturer recall notices. The inspection is visual verification against the vehicle condition at the time of inspection. It is buyer's responsibility to assess the vehicle at the point of sale.

The representative or company will not be responsible for the terms of any agreement or transaction or conversations between any persons in relation to any vehicle inspected. The representative or company will not be responsible for resolving disputes between parties in relation to any transactions.

Subject to all applicable laws, the representative or company does not provide any guarantee, warranty or representation regarding the nature, reliability, accuracy or completeness of any information contained in the inspection or the fitness of the information contained in the inspection for any purpose intended.